

FIG. 1





FIG. 1

119.0



244

242

246

- NewTest
- Annotations
- Lighting
- Plane1
- Plane2
- Plane3
- Origin
- (1) axis<1>
- (1) SLIDER<1>
- (1) SLIDER<2>
- (1) CRANK<1>
- (1) CRANK<2>
- MateGroup1

SW SolidWorks 2001 - [NewTest.SLDASM]

File Edit View Insert Tools Window Help

Microsoft

12:00 PM

Exploding Assembly

SolidWorks 2001

Microsoft

SPL Database

Exploding My Comp

Help: Assembly

Command Prompt

Exploding My Comp

Microsoft Office


Start

Ready

119.0

244

306



304

- New Test
- Annotations
- Sheet1
- Drawing View2
- Drawing View6




Fig. 4




FIG. 5

600




FIG. 6

702 Fig. 7

702

718

704

706

714


716

718

708

710

712



Select a component and drag to move it

FIG. 8




FIG. 8



FIG. 9




FIG. 9




FIG. 10

FIG. 11




FIG. 11

1202 → T03000" 46212600




Fig. 12

1302




Fig. 13

FIG. 14




FIG. 14




FIG. 15

FIG. 15